

路虎3.0/5.0汽油发动机主要存在的问题

Main issues with Land Rover 3.0/5.0 gasoline engines

Y型管问题

Y-shaped pipe problem



问题：Y型管结构容易导致漏水的原因

Problem 1: The reason why Y-shaped pipe structure is prone to water leakage

问题：Y型管胶圈设计结构过于简陋，容易导致微变形

The design structure of the Y-shaped pipe rubber ring is too simple, which can easily lead to slight deformation



Y型管问题解决方案

Solution to Y-shaped pipe problem

① 改变胶圈结构，增大摩擦面


Change the structure of the rubber ring to increase the friction surface

② 改变材料结构，使压缩比变小

Change the material structure to reduce the compression ratio

③ 或增加多重密封，增强锁水强度

Or add multiple seals to enhance water locking strength





曲轴后油封问题

Rear oil seal problem of crankshaft

该款引擎维修过程中容易出现曲轴后油封安装不当导致漏油

During the maintenance process of this engine, improper installation of the crankshaft rear oil seal can easily lead to oil leakage



© Copyright, 2016. Jaguar Land Rover Limited.


3030105
08-2013
30HD00
C0245700-01

曲轴后油封解决方案

Solution for crankshaft rear oil seal

制作两条限位杆平衡限位，辅助安装

Make two limit rods to balance the limit and assist in installation



高压油泵问题

High pressure oil pump issue

高压油泵易漏汽油使机油变稀，从而已导致轴瓦拉伤

The high-pressure oil pump is prone to leaking gasoline, causing the engine oil to become thinner, which has led to bearing strain



高泵油泵解决方案

增强其胶圈氟胶性能，抗汽油，抗乙二醇，使其不容易变形

Enhance the fluorine rubber performance of its rubber ring, resist gasoline and ethylene glycol, making it less prone to deformation





感谢聆听

Thank you for listening